



UNITED STATES PATENT AND TRADEMARK OFFICE

UNITED STATES DEPARTMENT OF COMMERCE
 United States Patent and Trademark Office
 Address: COMMISSIONER FOR PATENTS
 P.O. Box 1450
 Alexandria, Virginia 22313-1450
www.uspto.gov

BIBDATASHEET

Bib Data Sheet

CONFIRMATION NO. 7999

SERIAL NUMBER 10/733,213	FILING DATE 12/11/2003 RULE	CLASS 376	GROUP ART UNIT 3641	ATTORNEY DOCKET NO. 12093/929
-----------------------------	---------------------------------------	--------------	------------------------	-------------------------------------

APPLICANTS

George S. Pabis, Lynchburg, VA;

Anthony A. Pugh, Forest, VA;
Raymond A. King, Lynchburg, VA;Darel R. Clark, Lynchburg, VA;*None*

** CONTINUING DATA *****

None

** FOREIGN APPLICATIONS *****

Foreign Priority claimed	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no	STATE OR COUNTRY	SHEETS	TOTAL CLAIMS	INDEPENDENT CLAIMS
35 USC 119 (a-d) conditions met	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no <input type="checkbox"/> Met after allowance	VA	3	10	2
Verified and Acknowledged <i>John Rutherford Oct 28 2003</i>	Examiner's Signature <i>John Rutherford</i>	Initials <i>Oct 28 2003</i>			

ADDRESS

26646
 KENYON & KENYON
 ONE BROADWAY
 NEW YORK , NY
 10004

TITLE

Fuel assembly top nozzle repair sleeve and method for repairing a fuel assembly

FILING FEE RECEIVED 900	FEES: Authority has been given in Paper No. _____ to charge/credit DEPOSIT ACCOUNT No. _____ for following:	<input type="checkbox"/> All Fees <input type="checkbox"/> 1.16 Fees (Filing) <input type="checkbox"/> 1.17 Fees (Processing Ext. of time) <input type="checkbox"/> 1.18 Fees (Issue) <input type="checkbox"/> Other _____ <input type="checkbox"/> Credit
-------------------------------	---	---

Credit

10/733213 Examiner: RICHARDSON, JOHN GAU: 3641
Classification: 376/203.000 Inventor: PABIS , GEORGE, et al
Status: 30 - DOCKETED NEW CASE - READY FOR EXAMINATION
Title: FUEL ASSEMBLY TOP NOZZLE REPAIR SLEEVE AND METHOD FOR REPAIRING A FUEL ASSEMBLY

Bib Data report

Application Title:FUEL ASSEMBLY TOP NOZZLE REPAIR SLEEVE AND METHOD FOR REPAIRING A FUEL ASSEMBLY

Application Num:  (in phx) 10733213 **Filing Date:**12/11/2003

Effective Filing:12/11/2003

(Location History) (Foreign/Continuity Data)

Status: 30/DOCKETED NEW CASE - READY FOR EXAMINATION **Status Date:**
04/28/2004

Patent Number: Not Issued **Issue Date:** N/A **Date of Abandonment:** N/A
Confirmation Number:7999 **PALM Location:**

Examiner: 77495 RICHARDSON, JOHN (Assignment Data) **Group Art Unit:**
3641 **Class/Subclass:** 376/203.000

State or Country:VIRGINIA **Sheets/Drawing:** 3 **Total Claims:**10
Independent Claims:2

▼ **Inventors:**

Last name, First name:	City:	Country or State:
<u>PABIS, GEORGE</u>	LYNCHBURG	VIRGINIA
<u>PUGH, ANTHONY</u>	FOREST	VIRGINIA
<u>KING, RAYMOND</u>	LYNCHBURG	VIRGINIA
<u>CLARK, DAREL</u>	LYNCHBURG	VIRGINIA

Attorneys: ALL **Attorney Docket No:**12093/929

Interference No: **Lost Case:**No **Unmatched Petition:**No **L&R Code:**3